

## **CAP Inspection Log**

**Property Inspected:** Union Pacific Railroad Parcel B – Harbor Island, WA

**Date/Time of Inspection:** 28 December 2017, 0910-0915

**Name of Inspector:** Scott Adamek, PE

**Weather Conditions:** Overcast, damp, about 42 deg F

### **Pavement Cap Inspection**

**General:** The UPRR parcel observed is entirely capped with railroad ballast and is compliant with EPA requirements (see attached Figure 1 – Site Plan and attached photograph log).

**Pavement Cap Damage-Location and Description:** No pavement cap damage was observed.


**Standing water:** No standing water was observed.

**Settlement:** No obvious sign of differential settlement of more than 1-inch was observed on the cap.

**Changed Conditions:** No changes were noticed from the previous inspection that was performed in 2016.

### **Notes**

The area inspected is an active rail yard.



## Legend

- XXXXXX Fence
- UPRR Parcel Boundary
- +++++ Railroad Track

Figure 4 - Site Plan

Conditions on 28 December 2017  
 Start ~ 0910  
 End ~ 0915  
 Light rain, overcast  
 ~ 42°F

FIELD PHOTOGRAPHY LOG SHEET  
2017 UPRR Cap Inspection – Harbor Island (Parcel B)  
Seattle, Washington

December 28, 2017

Photograph No. 1

Photographed By:  
Scott Adamek

Description: View near southwest corner of UPRR Parcel B. View is towards the north-northeast.



---

December 28, 2017

Photograph No. 2

Photographed By:  
Scott Adamek

Description: View from near northern edge of UPRR Parcel B looking towards the southeast.

